US ERA ARCHIVE DOCUMENT

1. Incident Name		2. Date Prepared		3. Time Prepared	UNIT LOG	
Kalamazoo River/Enbridge Spill		06/01/2012		1850	ICS 214	
4. <u>Unit Name/Designators</u>		5. Unit Leader			6. Operational Period :	
SOTF Team #6		Name:	Dan Capone & Joe Victory (START/US EPA)		From:	06/01/2012 0858
		Position:	Operations Section Chief		То:	06/01/2012 1800
		7. Pe	rsonnel F	Roster Assigned		
<u>Name</u>		ICS Position		DUTY CELL		
Dan Capone		Operations Section Chief				
Joe Victory		Operations Section Chief				
Dan Zahner		Field Team Lead				
Kevin Johnson		SOTF#6				
	1	1	8. Acti	vity Log		
					LAT	LAT
		nstream of delta control point.			Various	Various
rictivity riica	MP 37.50, 37.	75 upstream	of delta	control point	(DD.MMMM)	(DD.MMMM)
OIL OBSERVED	EXTENT OF OIL IMPACTED AREA DENSITY OF OIL /SHEEN			NA NA		
Total Collection Points	NA NA			1171		
Total Boom Deployed	NA					
	START SOTF Team 6 Activity:					
Activity	SOTF#6 Kevin Johnson (START), Enbridge Team Lead Loren CaSale, and Leica operator Amber McDougal performed poling at 48 total locations. With 38 locations within focus area 37.75 (downstream of E4 control point) and 10 locations within 37.50 (upstream of E4 control point). A total of 14 locations had an overall submerged oil category of heavy, 16 locations had an overall submerged oil category of moderate, and 15 locations had an overall submerged oil category of light. Three locations had no signs of submerged oil. Generally, more light oil sheen was observed along areas of sand/gravel substrate					
	associated with the central river channel with more moderate and heavy oil sheen observed along silt/soft substrate adjacent to central river channel. Globules up to 1.0 cm were identified in locations having soft and silt based substrate. Twenty-nine locations SOTF #6 visited registered above the minimum temperature requirement of 60 degrees F. Nineteen locations indicated temperature readings below 60					
degrees F. Observed temperatures ranged from 58.6 to 65.2 degrees leading operations were not significantly impacted by vegetation or en					-	onmental

	conditions within focus areas. SOTF#6 was able to successfully navigate to all tasked poling reassessment locations.
Health and Safety	None
Issues	
Comments	